

OFF Munin

Acid-based shadow remover

Approved by Byggsvarubedömningen, Sunda Hus, Chemsoft and Trafikverket

Range of application:

Liquid acid for shadow removal. Use only on surfaces that can withstand acids.

How to use:

Apply with a brush or roller. Allow to take effect, approx. 1-3 min. Rinse with water. A suitable temperature and pressure would normally be 90°C and 90-150 bar pressure, depending on the surface type. If there are any remaining shadows, apply OFF Munin again and leave until the shadows are gone and then rinse off.



Containers: 10 or 25 litre, can

Storage: Frost-free in original packing

Dosage: Concentrate

pH value: 1

Consumption: Approx. 0,1-0,4 litre/m²

ADR: Not classified as dangerous goods if transported by road or by rail

Precautions:

Ensure good ventilation. Irritates eyes and skin.

Use protective clothing, gloves and glasses or visor in risk of contact

Eye wash facilities and emergency shower must be available when handling this product.

For more information please see the Safety Data Sheet for this particular product.

This product information is intended only as a guideline. MPE International does not accept responsibility for the end result. If in doubt, contact MPE International for advice.

MPE International AB
Dalagatan 3B
S-803 10 Gävle, Sweden

Phone:
+46(0)8-522 99 440

Email:
info@mpei.se

Web:
www.mpei.se

Org.nr:
556722-0420