

# TEST REPORT

**No: 54078**

Client **Panorama Antennas Pte Ltd**  
61 Frogmore  
Wandsworth  
London  
SW18 1HF

Client contact Anite Ramgi

Item/s tested **2 x antenna enclosures**  
Models: WMM(X)9G-24-58-NJ & WMM(X)9G-36-55-NJ  
Rating: IK10

Sample/s tested / Condition Two / Good condition


Tested to All relevant clauses of **BS EN 62262: 2002** IK10 (20J) and deemed to **comply**


Date sample received 15<sup>th</sup> May 2020

Test period 8<sup>th</sup> to 10<sup>th</sup> June 2020

Date of Issue 16<sup>th</sup> June 2020

Tests carried out at 20 ± 5 °C

Testing Officer  Stuart Mann

Verified by  Giuseppe Capanna



Form No: QF102-4  
Issue No: 1  
Issue Date: 07.01.14

<b>Report No:</b>	<b>54078</b>
<b>Client:</b>	<b>Panorama Antennas Pte Ltd</b>

THIS REPORT APPLIES ONLY TO THE PARTICULAR SAMPLE UNIT(S) TESTED AND TO THE SPECIFIC TESTS CARRIED OUT AS DETAILED IN THE PROJECT FILE HELD AT NEMKO LTD.

THIS REPORT DOES NOT COVER ELECTROMAGNETIC COMPATIBILITY.

IT SHOULD BE NOTED THAT ONLY A LIMITED NUMBER OF UNITS HAVE BEEN TESTED. IT IS THEREFORE ESSENTIAL FOR THE MANUFACTURER OR SUPPLIER OF THIS PRODUCT TO ENSURE THAT THE QUALITY OF ALL PRODUCTION UNITS IS TO THE SAME STANDARDS AS THAT OF THE SAMPLE (S) CHECKED.

### Photos of identification



### SUMMARY

The samples submitted for testing have been checked in accordance with the relevant clauses of: BS EN 62262: 2002

### BS EN 62262: 2002 (IK10)

6 Test to verify the protection against mechanical impacts (IK10)

**As a result of the above tests, the unit can be considered to comply in respect of the above Clauses**

**Condition / number of test sample :** Good / 2    **Serial Number(s) :-** None

**Notes relating to this report :-** (i) 3 x Impacts applied to each exposed surface

**Project History: -**

<u>Job Number</u>	<u>Sample received</u>	<u>Job Completion Date</u>	<u>Summary of work carried out</u>
54078	15-May-2020	10-Jun-2020	IK10 test only

----- End of Report -----