

Customer Testimonial...



JLM Diesel Air Intake & EGR Cleaner

The following data & case results were compiled by customers of JLM Distributors in Spain and Poland. In these case reports we briefly describe 3 cases of diesel cars that came into their workshop with EGR Problems

Case 1 - Mercedes C270 Cdi

Make : Mercedes C270 Cdi
Engine : 2.8
Year : 2000
Odometer : 156.000 km

Case from: JLM Distributor - Grupo Mecánico
Liquido - Spain

Tested by: Sr. Chano del Taller Hermanos Martel
Las Palmas de Gran Canarias

Problem:
Rough idling and slow response on throttle

Action:
Half a can of JLM Diesel Air Intake & EGR Cleaner was sprayed in to the EGR air Intake at 2000 RPM.

After treatment:
Mount and vanishes where cleaned, the fault light on the dashboard went off.

Before



After



Customer Testimonial...



Case 2 - Audi A4

Make : Audi A4
Engine : 1.9 TDI
Year : 2004
Odometer : 243.000 km

Case from: : JLM Distributor - Grupo
Mechánico Liquido - Spain

Tested by : Isaac Viñes - Motorsport Racing
Services, Bellvis, Lleida, Espana

Problem:
Low torque at low revs - black smoke when accelerating.

Action:
Half a can of JLM Diesel Air Intake EGR Cleaner was
Sprayed in to the EGR Intake at 2000 RPM.

After treatment the problem was solved

Before



After



Case 3 - Volkswagen Passat

Make : Volkswagen Passat
Engine : 1.9 TDI
Year : 1999
Odometer : 122.025 km

Case from: : A Polish JLM distributor
Tested by : Bosch Diesel Specialist
Problem : clogged EGR

Before



After

